Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137

BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					Expires: Ja	nuary 31, 2018	
					5. Lease Serial No. NMNM135989		
					6. If Indian, Allottee or Tribe Name EASTERN NAVAJO		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM137065A		
Type of Well					8. Well Name and No. BLANCO WASH UNIT 402H		
Name of Operator Contact: SHAW-MARIE FORD					9. API Well No.		
DJR OPERATING LLC E-Mail: sford@djrllc.com					30-045-35656-00-X1		
3a. Address 1600 BROADWAY SUITE 196 DENVER, CO 80202	3b. Phone No. (include area code) Ph: 505-632-3476			10. Field and Pool or Exploratory Area BASIN MANCOS			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 24 T24N R9W NESE 1569FSL 61FEL 36.296883 N Lat, 107.732113 W Lon					SAN JUAN COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OF	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	□ Нус	raulic Fracturing	☐ Reclam	ation		
Subsequent Report	☐ Casing Repair	□ Nev	Construction	☐ Recomp		☑ Other Drilling Operations	
☐ Final Abandonment Notice	☐ Change Plans			•	Drining Operations	3	
<b>6</b> 8	☐ Convert to Injection	☐ Plug		□ Water I			
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fi Intermediate Casing & Cemer 10/13/19: NU 11-inch 3K BOP	ally or recomplete horizontally, it will be performed or provide operations. If the operation re bandonment Notices must be fil inal inspection.	give subsurface the Bond No. o sults in a multip ed only after all	locations and measur n file with BLM/BIA. le completion or reco requirements, includi	ed and true ve Required sul impletion in a range reclamation	ertical depths of all pertin psequent reports must be new interval, a Form 316 n, have been completed a	ent markers and zones. filed within 30 days 0-4 must be filed once	
min. Test good recorded on Pason EDR. Short shell test low 250 psi for 5 min. High 3000 psi for min.: pipe rams, choke flex hose, all outer valves on choke manifold, 3rd party (Wilson Services) all tested good and recorded on chart. Drill ahead 8.75-inch hole to 2650 ft. 10/14/19: Drill 8.75-inch hole to 4792 ft. 10/15/19: Drill 8.75-inch hole to 5866 ft. TOOH 10/16/19: RU casing crew. Run 139 joints & 1 pup of 7-inch 26# J55 LTC casing set at 5856 ft. Fl Collar at 5810 ft. Circulate and condition for cement. 3500 psi test on lines. Test good. Cement					10	NMOCD	
with Halliburton (60% excess on both lead and tail). 10 bbls 7% KCL water spacer at 8.3# followed by 45 bbls tuned spacer at 11.5#, 3.67 yield, 23.8 gps. LEAD: 184 bbls (540 sx) at 12.3#, 1.91 yield, 5.81 gps. TAIL: 63 bbls (270 sx) at 13.5#, 1.3 yield, 5.81 gps. Displaced with 222 bbls FW.							
14. I hereby certify that the foregoing is	Electronic Submission #	PERATING LLC	, sent to the Farn	nington			
Name (Printed/Typed) SHAW-MA	Title REGULATORY SPECIALIST						
Signature (Electronic S	Submission)		Date 10/21/20	)19			
	THIS SPACE FO	OR FEDERA	L OR STATE (	OFFICE U	SE		
_Approved By_ACCEPTED			JOE KILLINS TitlePETROLEUM ENGINEER		Date 10/21/20	019	
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	Office Farmingt	on					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to ma	ake to any department or	agency of the United	

<sup>(</sup>Instructions on page 2)
\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



## Additional data for EC transaction #488911 that would not fit on the form

## 32. Additional remarks, continued

Bump plug at 2341 psi. Check floats. Floats held. 90 bbls good cement back to surface.