Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM54981 6. If Indian, Allottee or Tribe Name EASTERN NAVAJO	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM135203A	
Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. CROW CANYON UNIT 124H	
2. Name of Operator Contact: SHAW-MARIE FORD DJR OPERATING LLC E-Mail: sford@djrllc.com					9. API Well No. 30-045-38178-00-X1	
3a. Address 1600 BROADWAY SUITE 1960 DENVER, CO 80202 3b. Phone No. (include ar Ph: 505-632-3476				10. Field and Pool or Exploratory Area BASIN MANCOS		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 19 T24N R8W SESW 1085FSL 2064FWL 36.295559 N Lat, 107.724990 W Lon					11. County or Parish, State SAN JUAN COUNTY, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	F SUBMISSION TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	cidize		☐ Production (Start/Resume)		☐ Water Shut-Off
	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclama	ation	☐ Well Integrity
Subsequent Report	Casing Repair		v Construction Recom			☑ Other Drilling Operations
☐ Final Abandonment Notice			and Abandon Back	☐ Temporarily Abandon ☐ Water Disposal		
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Intermediate Casing & Cement 9/23/19: NU 11 inch 3K BOP (2M System) on pre-set 9.625 inch surface casing with installed 11 inch 5K Cameron wellhead. Test annular and TIW 250 low 5 min./1500 high 10 min. Test blind rams, HCR, pipe rams, kill valves, check valve, lower kelly, choke manifold and valves, full opening safety valve and the inside BOP valve at 250 psi low 5 mins. 3000 psi high 10 mins. Test surface casing 1500 for 30 min. Test good & recorded on chart (Wilson Services) Drill ahead 8.75 inch hole to 2557 ft. 9/24/19: Drill ahead 8.75 inch hole to 5038 ft. 9/25/19: Drill ahead 8.75 inch hole to 5771. TOH. RU casing crew. Run 176 jts. 26# J55 LTC 7 inch intermediate casing set at 5761 ft. Float collar at 5715 ft. 9/27/19: Cement with Halliburton (60% excess on both Lead and Tail) 3000 psi test on lines. 10 bbls						
14. I hereby certify that the foregoing is true and correct. Electronic Submission #485742 verified by the BLM Well Information System For DJR OPERATING LL¢, sent to the Farmington Committed to AFMSS for processing by OE KILLINS on 09/30/2019 (19JK0206SE) Name (Printed/Typed) SHAW-MARIE FORD Title REGULATORY SPECIALIST						
Signature (Electronic Submission) Date 09/30/2019 THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
				NS		
Approved By ACCEPTED			Title PETROLEUM ENGINEER		Date 09/30/2019	
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to condu	Office Farmington					
Fitte 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



Additional data for EC transaction #485742 that would not fit on the form

32. Additional remarks, continued

KCL water spacer @ 8.6# followed by 50 bbls tuned spacer at 11.5#, followed by Lead: 187.4 bbls (551 sx) at 12.3#, 1.91 yield, 10.02 gps. Tail: 63.2 bbl (273 sx) at 13.5#, 273 sks, 1.3 yield, 5.81 gps. Displace with 219 bbls FW. Bump plug with 2000 psi. Checked floats. Floats held. 60 bbls good cement to surface. Clear floor.