2

Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM54981		
							6. If Indian, Allottee or Tribe Name EASTERN NAVAJO
					SUBMIT IN TRIPLICATE - Other instructions on page 2		
1. Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. CROW CANYON UNIT 124H		
2. Name of Operator DJR OPERATING LLC E-Mail: sford@djrllc.com					9. API Well No. 30-045-38178-00-X1		
3a. Address 1600 BROADWAY SUITE 190 DENVER, CO 80202	3b. Phone No. (include area code) Ph: 505-632-3476		10. Field and Pool or Exploratory Area BASIN MANCOS				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, S		State		
Sec 19 T24N R8W SESW 100 36.295559 N Lat, 107.724990			SAN JUAN COUNTY, NM				
12. CHECK THE AI	PROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	Acidize		Deepen Pro		ion (Start/Resume)	UWater Shut-Off	
Subsequent Report	□ Alter Casing	- ,		Reclamation		U Well Integrity	
	Casing Repair			□ Recomplete		Other Drilling Operations	
Final Abandonment Notice	 Change Plans Convert to Injection 	Plug Plug Plug	g and Abandon Back	Temporarily Abandon Water Disposal		Drining opprations	
determined that the site is ready for final inspection. Production Liner & Cement 9/27/19: High 3,000 psi for 10 min: braden head, pipe rams, stinger flex hose, all outer valves in choke manifold, IBOP, grey valve. Low 250 psi for 5 min: braden head, pipe rams, stinger flex hose, all outer valves in choke manifold, IBOP, grey valve (Wilson Services). All tested good and recorded on chart. <u>PSI test 7 inch casing at 1500 psi for 30 min</u> . Test good. Recorded on Pason EDR. <u>Drill ahead 6,125 inch lateral to 6900 ft.</u> 9/28/19: Drill ahead 6.125 inch to 12,439 ft MD. TOH. RU casing crew. 9/30/19: Run 164 joints 4.5 inch 11.6# P110. BTC set as follows: Packer at (TOL) 5498, Hanger at 5521, XO at 5528, Pup at 5529, Marker 1 at 6403, Marker 2 at 8408, Marker 3 at 10429, Marker 4 at 12299, Alpha Sleeve at 12395, Pup at 12398, Landing collar at 12418, Float collar at 12419, Pup at 12420, Double Valve shoe at (BOL) 12430. RU cement crew. 5500 psi test on lines. Test good.							
14. I hereby certify that the foregoing is	Electronic Submission #	486176 verifie	d by the BLM Wel	I Information	ı System		
For DJR OPERATING LLC, sent to the Farmington Committed to AFMSS for processing by JOHN HOFFMAN on 10/04/2019 (20JH0007SE)							
Name (Printed/Typed) SHAW-MARIE FORD Tit				ATORY SP	ECIALIST		
Signature (Electronic Submission) Da				Date 10/02/2019			
	THIS SPACE FO	DR FEDERA	L OR STATE	OFFICE U	SE		
Approved By ACCEPTED			JOHN HOI TitlePETROLE		EER	Date 10/04/2019	
Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to condu-	d. Approval of this notice does uitable title to those rights in the		Office Farming	ton			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to ma	ake to any department or	agency of the United	
(Instructions on page 2) ** BLM REV	ISED ** BI M REVISEI		EVISED ** BL	REVISE	** BLM REVISE	D **	
		NMOC				_	
			Y			5	

Additional data for EC transaction #486176 that would not fit on the form

32. Additional remarks, continued

.

ł

10/01/2019: Cement with Halliburton (40% excess) 163 bbls (672 sx) ExtendaCem Class G, 13.3 ppg, 1.36 yield, 6.01 gps. Displace with 145 bbls MMCR, followed by 135 bbls FW with Bellacide. Bump plug with 1530 psi. Floats held. Pressure test packer 750 psi. Test good. <u>30 bbls good cement back</u> to surface. TOC: 5498 BOC: 12430. Rig Release at 00:00 V