



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOCd

OCT 23 2019
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10.22.19 Operator Pride Energy API #30-0 43-20721

Property Name San Isidro 12 Well No. 2 Location: Unit B Section 12 Township 20 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 1A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Bradenhead Int	Csg	INTERM Int	Csg	
TIME	<u>0</u>		<u>0</u>			
5 min	<u>0</u>		<u>0</u>			
10 min	<u>0</u>		<u>0</u>			
15 min	<u>0</u>		<u>0</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing	<u>/</u>	
Nothing	<u>/</u>	
Gas	<u>/</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

blow to dead at 5 seconds. Nothing
when opened after 5 min shut in

By Jafmy Brown
P.E.C. Pumpers
(Position)

Witness Monica Kuchling

E-mail address _____