NEW MEXICO ENERG & NATURAL RESOUR	
OCT 30 2019 DISTRICT III (submit 1 copy to above address)	
Date of Test07	erator BlackHawk Energy API #30-0 39-26731
Property Name_Jicarilla 29-03-11 Well No. 2 Location: Unit <u>H</u> Section <u>11</u> Township <u>29N</u> Range <u>3W</u>	
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 26 Bradenhead 0	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH IntCsgInt Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 0 26	Steady Flow
10 min 0 26	Surges
15 min 0 26	Down to Nothing
20 min	Nothing X
25 min	Gas
30 min	Gas & Water
-+ <u>-</u>	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A	
REMARKS:	
Opened Bradenhead on 10/16/19 had nothing on it.	
By_ <b>Donny Snell</b>	Witness
Lease Operator (Position)	
E-mail address dsnell@blackhawkenergycorp.com	