



NEW MEXICO DEPARTMENT OF
NATURAL RESOURCES

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/23/2019 Operator Blackhawk Energy API #30-0 39-30278
Property Name JIC 464-30 Well No. 724 Location: Unit H Section 30 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 38 Intermediate 0 Casing 260 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	260	0	260
10 min	0	0	260	0	260
15 min	0	0	260	0	260
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: H2S tube showed zero H2S on initial blow down.

BH had 0-psi on gauge, nothing else, Casing held steady at 260 psi. INT showed 0-psi on gauge with a 12 sec blow down and fumes for 5 sec after, nothing else.

By Robert Talamante
Plant/lease operator
(Position)

Witness _____

E-mail address rtalamante@blackhawkenergy.com

SEP 12 2019
DISTRICT III