



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOCD

AUG 07 2019

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III

Date of Test 7/10/19 Operator Enduring Resources LLC API #30-0 06868

Property Name Rincon Unit Well No. 149 Location: Unit Section Township Range

Well Status(Shut-In or Producing) Initial PSI: Tubing 33 Intermediate 413 Casing 51 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	Ø	413	51	1	48
10 min	Ø	413	48	Ø	47
15 min	Ø	413	48	Ø	50
20 min				Ø	51
25 min				Ø	53
30 min				Ø	54

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			✓
Surges			✓
Down to Nothing	✓		
Nothing			
Gas	✓		✓
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE 5

REMARKS: - Bradenhead blow one minute on needle valve and
thirty seconds on 1/2 inch, light blow after shut in - int down to low surge after 30 min
- gas sample to be requested: tubing, casing, int. - int down to zero, light blow

By John Dackter

Witness Monica Lucking

HSE tech
(Position)

E-mail address JDackter@EnduringResources.com

- wasnt blow down prior to testing per Monica Request

7/30/19