



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/26/19 Operator ENDURING RESOURCES IV LLC API #30-039-21066

Property Name: JICARILLA B Well No: 023 Location: Unit P Section 05 Township 24N Range 05W

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 81 Intermediate N/A Casing 2 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					FLOW CHARACTERISTICS	
	BH	Bradenhead Int	Csg	INTERM Int	Csg	BRADENHEAD	INTERMEDIATE
5 min	<u>Ø</u>		<u><1</u>				
10 min	<u>Ø</u>		<u><1</u>				
15 min	<u>Ø</u>		<u><1</u>			<u>✓</u>	
20 min							
25 min						<u>✓</u>	
30 min							

Steady Flow _____

Surges _____

Down to Nothing ✓

Nothing _____

Gas ✓

Gas & Water _____

Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE N/A

REMARKS:

Bradenhead blew down to 10 pressure as casing pressure dropped to near zero as well

By [Signature]
HSE Tech
(Position)

Witness _____

WMSD

SEP 04 2019

DISTRICT III

E-mail address JDockter@EnduringResources.com

9/3/19