



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/31/17 Operator ENDURING RESOURCES IV LLC API #30-039-31247

Property Name: NE CHACO COM Well No: 199H Location: Unit L Section 08 Township 23N Range 06W

Well Status(Shut-In or Producing) Initial PSI: Tubing 48 Intermediate N/A Casing 221 Bradenhead 20

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>Ø</u>		<u>220</u>		
10 min	<u>Ø</u>		<u>216</u>		
15 min	<u>Ø</u>		<u>214</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<input checked="" type="checkbox"/>	
Nothing		
Gas	<input checked="" type="checkbox"/>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD <1 INTERMEDIATE N/A

REMARKS:

New down, test after 9:31am, 7/31/17

- opened during test

- bradenhead blew down to nothing in approx 4 seconds

By John Dexter
HSE Tech
(Position)

Witness _____

E-mail address JDexter@EnduringResources.com

NMOC
AUG 12 2019
DISTRICT III

8/9/19