



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District II/3district.htm](http://emnrd.state.nm.us/ocd/District%20II/3district.htm)

NMOCd

DEC 16 2019

DISTRICT II

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-13-19 Operator DJR Petroleum LLC API #30-0 43-20513

Property Name Chacon Arroyos Well No. 6 Location: Unit A Section 11 Township 22 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 194 Intermediate N/A Casing 202 Bradenhead 47

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead		INTERM			
	BH	Int		Int	Csg	
TIME						
5 min	<u>4</u>				<u>208</u>	
10 min	<u>3</u>				<u>209</u>	
15 min	<u>3</u>				<u>210</u>	
20 min	<u>2</u>				<u>211</u>	
25 min	<u>2</u>				<u>212</u>	
30 min	<u>1</u>				<u>213</u>	

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 13

INTERMEDIATE N/A

REMARKS:

Hard blow when opened through 30 minute
test. Gas samples taken

By Jacob Harker
Consultant
(Position)

Witness Mona Kuehn
Joe J. G. A.

E-mail address jharker@coltonwoodconsulting.com