

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	6-13-19 Operato	r BPX	API# 3654516694
Property Name Case B 3 Location: Unit M Section 17 Township 31 Range 11			
Pressure (Shut-in or Producing) Tubing 71 Intermediate 6 Casing 92 Bradenhead 27.2			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
Time 5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes 5 minute SI	Bradenhead BH Casing Intermediate Monitor SQ SS S		Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water NMUCU Black ISTRICT III
Samples faken: BH- 7098. Into not enough for sample. T- 7014, C- 7004. Whisper through out test with a slight decline. O.4 at 30 min. Whisper at end of test with no full blow down. Int light flow down to putting in 16 see			
By Eng Tech	genia Hamilton hnician (Position)	Witness	NMOCD Test Area: B 593