



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-14-19 Operator BPX API # 3004523191

Property Name Case B 44 Location: Unit H Section 18 Township 31 Range 11
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 58 Intermediate N/A Casing 59 Bradenhead 14

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	Ø	61	N/A	N/A	N/A	Steady Flow		N/A
10 minutes	Ø	60				Surges		
15 minutes	Ø	59				Down to Nothing	✓	
20 minutes						No Flow		
25 minutes						Gas	✓	
30 minutes						Gas and Water		
5 minute SI	Ø	59				Water		

NMOCD

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead Ø Intermediate N/A

REMARKS:

Samples taken: BH-7058, T-7013, C-77064. Whisper at start of test and faded off to no flow in 18 sec. Huft for 2 sec at end of 5 min shut-in. Compressor on site

By Eugenia Hamilton
Technician

Witness _____

(Position)