



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 12.18.19 Operator Hilcorp Energy Co. API # 30-0 45-30788
Property Name Ashcroft SWD Well # 1 Location: Unit 3 Sec 26 Twn 29 Rge 11

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal ☒
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

NMOCD
DEC 19 2019
DISTRICT III

Temporarily Abandoned Well (Y/N) (N) TA Expires: _____

Casing Pres. 4
Bradenhead Pres. 0
Tubing Pres. 59
Int. Casing Pres. 0

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 600 psi. for 30 mins. Test passed/failed

REMARKS:

fell to 599 and held for rest of test
Packer set
top of 6870
top of 6952

By Steven J. Javer
(Operator Representative)

Witness Monica Trevino
(NMOCD)

SWD
(Position)

Revised 02-11-02