

Submit One Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised November 3, 2011

WELL API NO. 30-045-07658
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Gallegos Canyon Unit
8. Well Number 170
9. OGRID Number 000778
10. Pool name or Wildcat Basin Dakota

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: ☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
BP America Production Company

3. Address of Operator
1199 Main Ave, Durango, CO 81301

4. Well Location
Unit Letter K : 1705 feet from the South line and 1777 feet from the West line
Section 35 Township 29N Range 12W NMPM _____ County San Juan

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
5381'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
	P AND A <input type="checkbox"/>
	CASING/CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	<input checked="" type="checkbox"/> Location is ready for OCD inspection after P&A

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- ☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- ☐ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. Location is in an agricultural field and has a below grade P&A marker to accommodate agricultural production.
- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- ☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- ☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- ☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- ☒ All other environmental concerns have been addressed as per OCD rules. Ground water monitor wells on location per OCD rules.
- ☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
- ☒ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection. **All work was completed on 4/21/2017**

SIGNATURE Sabre J. Beebe TITLE Compliance Specialist DATE January 28, 2020

TYPE OR PRINT NAME Sabre J. Beebe E-MAIL: sabre.beebe@bpx.com PHONE: 970-779-9398

For State Use Only

APPROVED BY: _____
Conditions of Approval (if

DENIED

NMOC

BY: Jonathan Kelly
DATE: 2/24/2020 (505) 334-6178 Ext. 122

Location has an open active groundwater case, which will need to be closed prior to site release. C-103 missing required photo of below grade P&A marker in place.

FEB 10 2020

DISTRICT III

BP L48 San Juan




Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Julian Martinez (julianmartinez)
Submission Date:	Jan 22, 2020 1:35:23 PM MST
Server Receive Date:	Jan 22, 2020 1:35:34 PM MST
Reference Number:	20200122-18130490787
Location:	209 Rd 5500, Bloomfield, NM 87413, USA Jan 22, 2020 1:31:08 PM MST [View Map]

Information

Name	julianmartinez
Date	Jan 22, 2020
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	GCU 170
Location Name (Other)	Gallegos Canyon Unit 170
Location API (Other)	3004507658
Select State	New Mexico
Work type	Plug & Abandonment Work
Action Complete	Grading/recontour Seeding Equipment Stripping

Photo of first corrective action completed



Completed work description Corrective Action 1
Photo of second corrective action completed

Equipment strip off complete - photo to West



Completed work description of corrective action 2
Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed



Completed work description
Completed work description of corrective action 4
Summary of all work completed

Equipment strip off complete - photo to North

Equipment strip off complete - photo to East

Equipment strip off complete - photo to South

Equipment strip off complete

Plug and Abandonment - strip off surface equipment complete