

Submit One Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised November 3, 2011

WELL API NO. 30-045-24179
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Gallegos Canyon Unit
8. Well Number Com 094 E
9. OGRID Number 000778
10. Pool name or Wildcat Basin Dakota

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: ☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
BP America Production Company

3. Address of Operator
1199 Main Ave, Durango, CO 81301

4. Well Location

Unit Letter A : 900 feet from the North line and 790 feet from the East line
Section 23 Township 29N Range 13W NMPM County San Juan

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
5325'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

☒ Location is ready for OCD inspection after P&A

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER,
SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE
MARKER'S SURFACE**

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other
production equipment.
☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the
terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be
removed.)
☒ All other environmental concerns have been addressed as per OCD rules.
☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines
and pipelines.
☒ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location,
except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection. All work was completed on 7/10/2019

SIGNATURE sabre.beebe@bpx.com Digitally signed by sabre.beebe@bpx.com
DN: cn=sabre.beebe@bpx.com
Date: 2020.01.28 11:29:32 -0700 TITLE Compliance Specialist DATE January 28, 2020

TYPE OR PRINT NAME Sabre J. Beebe E-MAIL: sabre.beebe@bpx.com PHONE: 970-779-9398

For State Use Only

APPROVED BY: [Signature]
Conditions of Approval (if any):

TITLE

AV

Deputy Oil & Gas Inspector,

District #3

DATE 26 Feb 2020

NMOCD

FEB 10 2020

DISTRICT III

BP L48 San Juan



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Julian Martinez (julianmartinez)
Submission Date: Jan 22, 2020 2:22:46 PM MST
Server Receive Date: Jan 22, 2020 2:22:54 PM MST
Reference Number: 20200122-18130501141
Location: 3121 Bloomfield Hwy, Farmington, NM 87401, USA
Jan 22, 2020 2:19:50 PM MST [[View Map](#)]

Information

Name	julianmartinez
Date	Jan 22, 2020
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	GCU 094E
Location Name (Other)	Gallegos Canyon Unit 094E
Location API (Other)	3004524179
Select State	New Mexico
Work type	Plug & Abandonment Work
Action Complete	Grading/recontour Equipment Stripping

Photo of first corrective action completed



Completed work description Corrective Action 1
Photo of second corrective action completed

Equipment strip off complete - Photo to the East



Completed work description of corrective action 2
Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed



Completed work description
Completed work description of corrective action 4
Completed work description
Summary of all work completed

Equipment strip off complete - Photo to the South

Equipment strip off complete - Photo to the West

Equipment strip off complete - Photo to the North
Plug and abandonment- equipment strip off complete
Plug and abandonment- equipment strip complete
Plug and abandonment- equipment strip off complete