UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

1. Type of Well GAS 2. Name of Operator BURLINGTON RESCURCES OIL & GAS COMPANY LP 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool GESE), 1025° FSL & 368° FEL, Sec. 38, T29N, R7W, NMPM 11. County and State Rio Arriba Co., NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Notice of Intent Abandomment Abandom	2. Name of Operator BURLINGTON RESCURCES OIL & GAS COMPANY LP 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 930 FNL 846 FWL 19 72W, P4W	JIC103 6. If Indian, All. Tribe Name 7. Unit Agreeme 8. Well Name & Jicarilla 103 # API Well No. 30-039-21774 10. Field and Poo	or ent Name Number
Tribe Name 7. Unit Agreement Na 8. Well Name & Numi 8. Well Name & Numi 9. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 9. API Well No. 30-039-21774 4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool 9. API Well No. 30-039-21774 11. County and State Rio Arriba Co., NN 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Notice of Intent Abandonment Abandonment Abandonment Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 3/24/06 MIRU Aztec #485. RD HH & seat pump. Lood hole & PT tbg to 1000#-0K. TIH w/pump & rods. NDWH, NU BOP. RIH & togged @ 7800'. M/O junk in hole for 3 days. TOH w/mill. TIH w/2-3/8", J-55 tubing (248 Jts) & set @ 77779' w/SN @ 7745'. ND BOP, NU WH. RIH w/pump & rods. Sepced out. PT pump & tbg - OK, RU HH.	2. Name of Operator BURLINGTON RESCURCES OIL & GAS COMPANY LP 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 930 FNL 846 FWL 19 72W, P4W	7. Unit Agreeme 8. Well Name & Jicarilla 103 # API Well No. 30-039-21774 10. Field and Poo	ent Name Number
2. Name of Operator BURLINGTON RESCURCES OIL & GAS COMPANY LP 8. Well Name & Num 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 9. API Well No. 30-039-21774 4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool GENERAL SHAFWL 19 TELN, PHW Unit P (SESE), 1025' FSL & 365' FEL, Sec. 36, T29N, R7W, NMPM 11. County and State Rio Arriba Co., NN 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Notice of Intent Abandonment Accompletion New Construction Non-Routine Fracturing Casing Repair Water Shu off Final Abandonment Altering Casing Conversion to Injection 3/24/06 MIRU Aztec #485. RD HH & seat pump. Load hole & PT tbg to 1000#-OK. TIH w/pump & rods. NDWH, NU BOP. RIH & tog 1/4 Tell W/2-3/8", tbg. Kill well w/2% KCL. RIH w/mill & togged @ 7800'. M/O junk in hole for 3 days. TOH w/mill. TIH w/2-3/8", J-55 tubng (248 jts) & set @ 7779 w/5N @ 7745'. ND BOP, NU WH. RIH w/pump & rods. Sepced out. PT pump & tbg - OK. RU HH.	BURLINGTON RESCURCES OIL & GAS COMPANY LP 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 930 FNL 846 FWL 19 - 72W, P4W	9. Well Name & Jicarilla 103 # API Well No. 30-039-21774	Number 10
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool ### Full Blanco MV Unit P (SESE), 1925' FSL & 365' FEL, Sec. 39, T29N, R7W, NMPM 11. County and State Rio Arriba Co., NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Notice of Intent	PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 930 FNL 846 FWL 19 - 726N, P4W	9. Jicarilla 103 # API Well No. 30-039-21774 10. Field and Poo	‡10
PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool ### PATEUR, PHUR Unit P (SESE), 1025' FSL & 368' FEL, Sec. 39, T29N, R7W, NMPM 11. County and State Rio Arriba Co., NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 3/24/06 MIRU Aztec #485. RD HH & seat pump. Load hole & PT tbg to 1000#-OK. TIH w/pump & rods. NDWH, NU BOP. RIH & tag fill. TIH w/2-3/8", tbg. Kill well w/2% KCL. RIH w/mill & tagged @ 7800'. M/O junk in hole for 3 days. TOH w/mill. TIH w/2-3/8", J-55 tubng (248 jts) & set @ 7779' w/SN @ 7745'. ND BOP, NU WH. RIH w/pump & rods. Sapced out. PT pump & tbg - OK. RU HH.	PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 930 FNL 846 FWL— 19 - TELN, P.4W	9. API Well No. 30-039-21774 10. Field and Poo	
4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool 435 FNL 846 FW - 772 W, P.HW Unit P (SESE), 1025' FSL & 365' FEL, Sec. 36, F29N, R7W, NMPM 11. County and State Rio Arriba Co., NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Notice of Intent Abandonment Change of Plans X Other - Casing Report Recompletion New Construction X Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 3/24/06 MIRU Aztec #485. RD HH & seat pump. Load hole & PT tbg to 1000#-OK. TIH w/pump & rods. NDWH, NU BOP. RIH & tag fill. TIH w/2-3/8", tbg. Kill well w/2% KCL. RIH w/mill & tagged @ 7800'. M/O junk in hole for 3 days. TOH w/mill. TIH w/2-3/8", J-55 tubng (248 jts) & set @ 7779' w/SN @ 7745'. ND BOP, NU WH. RIH w/pump & rods. Sapced out. PT pump & tbg - OK. RU HH.	930 FNL 840 FW = 19 - TELN, P.4W	10. Field and Poo	ı
Unit P (SESE), 1025' FSL & 365' FEL, Sec. 36, F29N, R7W, NMPM 11. County and State Rio Arriba Co., NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Notice of Intent Abandonment Recompletion None Construction Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 3/24/06 MIRU Aztec #485. RD HH & seat pump. Load hole & PT tbg to 1000#-OK. TIH w/pump & rods. NDWH, NU BOP. RIH & tag fill. TIH w/2-3/8", tbg. Kill well w/2% KCL. RIH w/mill & tagged @ 7800'. M/O junk in hole for 3 days. TOH w/mill. TIH w/2-3/8", J-55 tubng (248 jts) & set @ 7779' w/SN @ 7745'. ND BOP, NU WH. RIH w/pump & rods. Sapced out. PT pump & tbg - OK. RU HH.	930 FNL 840 FW = 19 - TELN, P.4W		ı
Unit P (SESE), 1025' FSL & 365' FEL, See: 30, T29N, R7W, NMPM 11. County and State Rio Arriba Co., NM. 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Notice of Intent Abandonment Recompletion New Construction New Construction Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 3/24/06 MIRU Aztec #485. RD HH & seat pump. Load hole & PT tbg to 1000#-OK. TIH w/pump & rods. NDWH, NU BOP. RIH & tagfill. TIH w/2-3/8", tbg. Kill well w/2% KCL. RIH w/mill & tagged @ 7800'. M/O junk in hole for 3 days. TOH w/mill. TIH w/2-3/8", J-55 tubng (248 jts) & set @ 7779' w/SN @ 7745'. ND BOP, NU WH. RIH w/pump & rods. Sapced out. PT pump & tbg - OK. RU HH.	• •	Blanco MV	
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Notice of Intent	Unit I (SESE), 1025 FSE & 305 FEE, Sec. 30, F2511, K/W, MINI W		
Type of Submission Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 3/24/06 MIRU Aztec #485. RD HH & seat pump. Load hole & PT tbg to 1000#-OK. TIH w/pump & rods. NDWH, NU BOP. RIH & tag fill. TIH w/2-3/8", tbg. Kill well w/2% KCL. RIH w/mill & tagged @ 7800'. M/O junk in hole for 3 days. TOH w/mill. TIH w/2-3/8", J-55 tubng (248 jts) & set @ 7779' w/SN @ 7745'. ND BOP, NU WH. RIH w/pump & rods. Sapced out. PT pump & tbg - OK. RU HH.		· · · · · · · · · · · · · · · · · · ·	
3/24/06 MIRU Aztec #485. RD HH & seat pump. Load hole & PT tbg to 1000#-OK. TIH w/pump & rods. NDWH, NU BOP. RIH & tagfill. TIH w/2-3/8", tbg. Kill well w/2% KCL. RIH w/mill & tagged @ 7800'. M/O junk in hole for 3 days. TOH w/mill. TIH w/2-3/8", J-55 tubng (248 jts) & set @ 7779' w/SN @ 7745'. ND BOP, NU WH. RIH w/pump & rods. Sapced out. PT pump & tbg - OK. RU HH.	Type of Submission Notice of Intent Abandonment Recompletion X Subsequent Report Plugging Casing Repair Water Shut off	•	
	3/24/06 MIRU Aztec #485. RD HH & seat pump. Load hole & PT tbg to 1000#-OK. TIH fill. TIH w/2-3/8", tbg. Kill well w/2% KCL. RIH w/mill & tagged @ 7800'. M/O junk in h J-55 tubng (248 jts) & set @ 7779' w/SN @ 7745'. ND BOP, NU WH. RIH w/pump & rod	n hole for 3 days. TOH w/mill. TIH w/2-	-3/8", 4.7#
14. I hereby certify that the foregoing is true and correct. Signed Patsy Clugston Title Sr. Regulator Special SOR RECORD 4/6/06 (This space for Federal or State Office use)	Signed Patsy Clugston Title Sr. R (This space for Federal or State Office use)	JUN 0 1 2006	<u>4/6/06</u>
APPROVED BYTitle FARMINGTON FIEDDOFFICE		FARMINGTON FIEDD OFFICE	

NMOCD