

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)


BRADENHEAD TEST REPORT
(Submit 1 copies to above address)

Date of Test 05-17-06 Operator Dugan Production Corp. API # 30-045-05618
Property Name West Bisti Unit Well No. 156 Location: Unit J Section 36 Township 26N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 18 Intermediate NONE Casing 28 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes	<u>Ø</u>		<u>28</u>					
10 minutes	<u>Ø</u>		<u>28</u>					
15 minutes	<u>Ø</u>		<u>28</u>					
20 minutes						<u>X</u>		
25 minutes								
30 minutes								

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE _____

REMARKS:

By *[Signature]*
Switcher
(Position)

Witness _____