NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test	Date of Test OSCIPPS Operator				Dugan Production Corp.			API# <u>30-045-05684</u>				
Property Name West Bisti Unit			Well No _	127	_Location: Un	it <u>G</u>	_Section	28 Township	26N Rang	e <u>13W</u>		
Well Status(Shut-In or Producing) Initial PSI:					Tubing _	940	Intermedia <u>te</u>	NA	Casing _	<i>O</i> -	_Bradenhead_	8
OPEN BRA		D ANI		ERME	DIATE T	O ATMC	SPHERE IN	IDIVIDUAI	LY FOR	15 MINUTES	EACH	
Bradenhead Interm					FLOW CHARACTERISTICS							
TIME	BH Int	Csg	Int	Csg	1			BRAD	ENHEAD	INTERME	DIATE	
5 mintues	0	10			5	Steady Flow	_					
10 minutes	0	0			<u> </u>	Surges	_					
15 minutes	0	0] .	Down to No	othing				1000773	
20 minutes						Nothing			+			
25 minutes					,	Sas			į		T CO	- T.
30 minutes					1 ,	Sas & Wat	er	-		1	\$1	131 141
			II		4	Vater				1.50 m		* 7
										***		\$.
<u>lf bradent</u>	nead flov	<u>ved v</u>	vater	, che	ck all of	the de	scriptions	that app	ly below	<u>/:</u>		.*
		CLEAR	·		_FRESH_		SALTY	SULF	UR	BLACK	_	
5 MINUTE	SHUT-IN		BRAI	DENHE.	AD _	Ø	IN	TERMEDIAT	E			
recition in the co.												
							· · · · · · · · · · · · · · · · · · ·					
					·			<u> </u>				
		_										
									···			
		Dal		. 11 1	ally							
Ву				00	early !!		Wi	tness				
			(Posi	tcher			_					