

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnrd.state.nm.us/ocd/District.III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 05-19-06 Operator Dugan Production Corp. API # 30-045-13403
Property Name West Bisti Unit Well No. 131 Location: Unit J Section 28 Township 26N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead		Interm				BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes						Steady Flow		
10 minutes						Surges		
15 minutes						Down to Nothing		
20 minutes						Nothing		
25 minutes						Gas		
30 minutes						Gas & Water		
						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

T/A

By

[Signature]
Switcher
(Position)

Witness
