

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 5/23/06 Operator Dugan Production Corp. API # 30-045-30573
Property Name Camp David Com Well No. 2 Location: Unit O Section 36 Township 30N Range 14W
Well Status(Shut-In or Producing) Initial PSI: Tubing 60 Intermediate Casing 19 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

	Bradenhead			Interm	
TIME	BH	Int	Csg	Int	Csg
5 minutes	Ø		19		
10 minutes	Ø		19		
15 minutes	Ø		19		
20 minutes					
25 minutes					
30 minutes					

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
<u>Blew dead</u>	
<u>Down to nothing</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN

BRADENHEAD

Ø

INTERMEDIATE

REMARKS:

By

Jane [Signature] 38
Switcher
(Position)

Witness
