NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

	5/aulic							
Date of Test	5/24/06	Operator	Dugan Production	Corp.	_API# _3	30-045-305	92	
Property Name	Feder	al I	Well No. 4R	Location: Unit	D8	Section1	Township _	29N Range 14W
Well Status(Sh	ut-In or Producing)	Initial PSI:	Tubing 45	Intermediate —	(Casing	16	Bradenh <u>ead Ø</u>
TIME 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	DENHEAD AND PRESS Bradenhead BH Int Csg 16 0 16 0 16		Steady Flow Surges Down to Noth Nothing Gas Gas & Water	hing		HARACTERI	STICS INTERMEDI	
If bradenhead flowed water, check all of the descriptions that apply below:								
	CLEAR		FRESH	SALTY	_SULFUR_	BLA	CK	
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE								
Ву	Jesus	Switcher	<u> </u>	Witness	s			

(Position)