

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)


BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 6-8-06 Operator Dugan Production Corp. API # 30045-24021
Property Name Mexico Federal M Well No. 1A Location: Unit P Section 12 Township 31N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 180 Intermediate NA Casing 160 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead		Interm				BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes	0					Steady Flow	NA	
10 minutes						Surges		
15 minutes						Down to Nothing		
20 minutes						Nothing		
25 minutes						Gas		
30 minutes						Gas & Water		
						Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

The Bradenhead Blew Down to Nothing in Less than 5 seconds,

By Michel D. Bimbel Witness _____
Switcher
(Position)