

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copies to above address)

Date of Test 6-19-6 Operator Dugan Production Corp. API # 30-045-27822  
Property Name Calgary Well No. 6 Location: Unit K Section 6 Township 23N Range 10W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 60 Intermediate          Casing 45 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0		45		
10 minutes	0		45		
15 minutes	0		45		
20 minutes	0		45		
25 minutes	0		45		
30 minutes	0		45		

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE



**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR          FRESH          SALTY          SULFUR          BLACK         

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE         

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By mtg Sued  
\_\_\_\_\_  
Switcher  
(Position)

Witness