NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 4-28-0 Coperator	Dugan Production Corp.	API# 30-045	-32704
Property Name Elmo Com			
Well Status(Shut-In Producing) Initial PSI:	-		
OPEN BRADENHEAD AND INTERMED PRESSURE Bradenhead Interm TIME BH Int Csg Int Csg 5 mintues //5 10 minutes	EDIATE TO ATMOSPHERE INDI Steady Flow Surges	VIDUALLY FOR FLOW CHARACT BRADENHEAD	
15 minutes	Down to Nothing		245678
20 minutes	Nothing	\times	
25 minutes	Gas		
30 minutes	Gas & Water		377
	Water		E. Dist. 8
If bradenhead flowed water, check all of the descriptions that apply below:			
CLEAR	FRESHSALTY	SULFUR	BLACK
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE REMARKS:			
By Switcher (Position)	Witne	ss	