


Deviation Report

Name of Company Burlington Resources Oil & Gas Company	Address P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number (API Number) SAN JUAN 29-7 UNIT #33C (30-039-29793)	Location 1330 FNL 2465 FEL	Sec. Twn. Rge. 13-029N-007W
Pool and Formation DAKOTA	County RIO ARriba	State NEW MEXICO

(Bud's Mess)

<u>Depth (ft)</u>	<u>Deviation (degrees)</u>
3,639	0.29
3,731	3.07
3,775	12.71
3,844	12.70
3,875	13.10
3,907	12.80
3,938	11.78
4,001	10.90
4,033	10.40
4,096	8.47
4,200	6.90
4,393	4.00
4,675	1.75
5,170	2.00
5,546	1.00
6,045	1.00
6,539	0.50
7,035	1.50
7,408	1.75
7,590	1.50



Air Hammer Used? YES / NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

A handwritten signature in black ink, appearing to be "J. L. ...", written over a horizontal line.

Subscribed and sworn to before me this 20th day of July, 2006.

A handwritten signature in black ink, reading "Patricia L. Chisler", written over a horizontal line.

Notary Public in and for San Juan County, New Mexico

My commission expires September 15, 2008.

86