

72

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 6-28-06 Operator Dugan Production Corp. API # 30-045-29239
Property Name Buddha Temple Well No. 90 Location: Unit A Section 30 Township 24N Range 8W
Well Status(Shut-In or Producing) Initial PSI: Tubing 80 Intermediate Casing 80 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		80			
10 minutes	0		80			
15 minutes	0		80			
20 minutes	0		80			
25 minutes	0		80			
30 minutes	0		80			

Steady Flow

Surges

Down to Nothing

Nothing

Gas


Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

BRADENHEAD	INTERMEDIATE



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

By *[Signature]*

Witness

Switcher

(Position)