



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
 Aztec District Office  
 1000 Rio Brazos Road  
 Aztec, NM 87410  
 (505)334-6178 FAX:(505)334-6170

[http://emrmd.state.nm.us/ocd/District\\_III/3district.htm](http://emrmd.state.nm.us/ocd/District_III/3district.htm)

**BRADENHEAD TEST REPORT**  
 (Submit 1 copy to above address)

Date of Test 07-26-06 Operator Dugan Production Corp. API # 30-045-23847  
 Property Name Dome Navajo 21-27-13 Well No. 3 Location: Unit M Section 21 Township 27N Range 13W  
 Well Status(Shut-In or Producing) Initial PSI: Tubing 370 Intermediate N/A Casing 35.2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0		35		
10 minutes	0		35		
15 minutes	0		35		
20 minutes	0		35		
25 minutes	0		35		
30 minutes	0		35		

FLOW CHARACTERISTICS

Steady Flow  
 Surges  
 Down to Nothing  
 Nothing  
 Gas  
 Gas & Water  
 Water

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<input checked="" type="checkbox"/>	
Gas		
Gas & Water		
Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

By John [Signature]  
 Switcher  
 (Position)

Witness \_\_\_\_\_