

Deviation Report

Name of Company Burlington Resources Oil & Gas Company	Address P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number (API Number) FARMINGTON COM #1F (30-045-33632)	Location -770 FSL -1935 FWL	Sec. Twn. Rge. 36-031N-013W
Pool and Formation BASIN DAKOTA	County SAN JUAN	State NEW MEXICO

(OH)

<u>Depth (ft)</u>	<u>Deviation (degrees)</u>
250	1.00
500	1.00
935	0.25
1,439	1.00
1,920	1.00
2,069	1.00
2,568	1.00
3,292	2.00
3,579	1.50
3,879	2.75
4,591	1.50
4,774	2.00
5,092	2.00
5,302	2.00
5,837	1.75
6,865	1.75



Air Hammer Used? YES NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 23rd day of AUGUST, 2006.

Armanda Sainz

Notary Public in and for San Juan County, New Mexico

My commission expires March 20, 2010.