

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8/14/06 Operator ROBERT L. BAYLESS, PRODUCER, LLC API #30-0 45-21745				
Property Name NAVAJOTRIBALP Well No. 6 Location: Unit 0 Section 7 Township 26N Range 18W				
Well Status (Shut-In or Producing) Tubing 200 Intermediate 6 Casing 90 Bradenhead 6				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
TIME BRADEN	PRESSURES: NHEAD INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes <u>C</u>)	90	Steady Flow	
10 minutes	, 0	90	Surges	
15 minutes 6		90	Down to Nothing	
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK			SULFURBLACK	ED seeps
5 MINUTE SHUT-IN BRADENHEAD REMARKS:			INTERMEDIATE SEP 2006	
				22.13.M. V. J.
By Palmer Knepp Pumper			Witness_	
PUMPe (Position)				
E-mail address		···		