

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test Operator ROBERT L. BAYLESS, PRODUCER, LLC API #30-045-31709						
Property Name MARRON Well No. 10 Location: Unit D Section 24 Township 27N Range 8W						
Well Status (Shut-In or Producing) Tubing 3 Intermediate Casing 18 Bradenhead 0						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	BRADENHEAD	PRESSURES: INTERMEDIATE	CASING	_	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes_	0		18	Steady Flow		· · · · · · · · · · · · · · · · · · ·
10 minutes_	0		18	Surges		
15 minutes_	0		18	_ Down to Nothin	g	
20 minutes_	0		18	Nothing	×	
25 minutes_	0		18	Gas		
30 minutes_	0		18	Gas & Water		
				Water		
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD				INTERMEDIATE	- (S) <b>SE</b>	2008 TA
REMARKS:						
						CHE WEST
By Du MAe (Position)				Witness		
E-mail address						