

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 8/17/06 Operator Dugan Production Corp. API # 30-045-29650  
Property Name Merry Chase Well No. 90 Location: Unit N Section 10 Township 24 Range 9W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 5 Intermediate 0 Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg	BRADENHEAD	INTERMEDIATE
5 minutes	0		30			Steady Flow	
10 minutes						Surges	
15 minutes	0		30			Down to Nothing	
20 minutes						Nothing	
25 minutes	0		30			Gas	
30 minutes						Gas & Water	
						Water	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

By

[Signature]  
Switcher  
(Position)

Witness

