



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

8/16/06

Operator

LUCKY WASH

API #

30-045-28355

~~713-658-1888~~

Property Name

ANGEL PRAK 1H#20

Location: Unit

H

Section

1

Township

T27N

Range

R10W

(Well Name and Number)

Pressure (Shut-in or Producing)

Producing

Tubing

7

Intermediate

—

Casing

30

Bradenhead

0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Bradenhead		
BH Blowdown	Casing Monitor	Intermediate Monitor
5 minutes	36	
10 minutes	36	
15 minutes	36	
20 minutes	36	
25 minutes	36	
30 minutes	36	
5 minute SI	36	

Intermediate	
Intermediate Blowdown	Casing Monitor

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing		
No Flow	✓	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur — Black —

5 Minute Shut-in Bradenhead 0 Intermediate —

REMARKS:

by LUCKY WASH
PUMPER
(Position)

Witness