

RCVD OCT25'06
OIL CONS. DIV.
DIST. 3

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnrd.state.nm.us/ocd/District III/3district.htm>

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

Date of Test 8-17-06 Operator Dugan Production Corp. API # 30-045-24235
Property Name Kingfish Well No. 1 Location: Unit G Section 3 Township 26N Range 13W
Well Status(Shut-In or Producing) (Producing) Initial PSI: Tubing 63.5 Intermediate N/A Casing 64.5 Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead		Interm				BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes								Steady Flow
10 minutes								Surges
15 minutes								Down to Nothing
20 minutes								Nothing
25 minutes								Gas
30 minutes								Gas & Water
								Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD N/A INTERMEDIATE N/A

REMARKS:

NO Braden head

By

[Signature]

Witness _____

Switcher
(Position)