

RCVD OCT 25 '06
OIL CONS. DIV.
DIST. 3

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 8-22-06 Operator Dugan Production Corp. API # 30-045-30310
Property Name Dome Navajo 13-26-13 Well No. 1R Location: Unit I Section 13 Township 26N Range 13W
Well Status(Shut-In or Producing) Producing Initial PSI: Tubing 0 Intermediate N/A Casing 31 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0		31		
10 minutes	0		31		
15 minutes	0		31		
20 minutes					
25 minutes					
30 minutes					

FLOW CHARACTERISTICS

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

NO brad en head

By

Dora M N

Witness _____

Switcher

(Position)