RCVD OCT30'06 OIL CONS. DIV. DIST. 3

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-35-0	Operator M&G Drilling	Company	API #3	0-0 45-07146	
Property Name	KRAUSE	Well No.	Location: Unit L	Section	29 Township	28N Range 11W
Well Status (Shut-)	n or Producing)	Tubing 272	Intermediate	Casing	133 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
тіме	PRESSURES: INTERMEDIATE	CASING			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		193	Steady Flow		0_	
10 minutes	-	137	Surges			
15 minutes		133	Down to Nothing	•		
20 minutes			Nothing			
25 minutes			Gas			
30 minutes			Gas & Water			
			Water			
If bradenhead flowed water, check all of the descriptions that apply below:  CLEAR FRESH SALTY SULFUR BLACK  5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE  REMARKS:						
By DAVIORORK Witness						

(Position)