RCVD OCT30'06 OIL CONS. DIV. DIST. 3

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	913-06	Operator M&G Di	rilling Company	AP	I #30-0 <u>45-32484</u>		
Property Name	KRAUSE	Well No.	33 1038 Location: Unit	C Section	33 Township	Range	11W
Well Status (Shut	-In or Producing)	Tubing//	Intermediate	Casing	Bradenhead	0	
	OPEN BRA	ADENHEAD AND IN	TERMEDIATE TO ATMOS	PHERE INDIVID	UALLY FOR 15 MIN	UTES EACH	
	PRESSURES:				BRADENHEAD	INTERMEDIATE	
TIME	INTERMEDIATE	CASING	<del>_</del>		FLOWED	F	LOWED
5 minutes		P	Steady Flow	<u></u>			
10 minutes		8	Surges				
15 minutes		8	Down to Nothing				
20 minutes			Nothing		0		
25 minutes	1		Gas	<u></u>			
					· · · · · · · · · · · · · · · · · · ·		
30 minutes		L	Gas & Water	<u></u>			
			Water				
If bradenhead flo	wed water, check all of the	descriptions that apply l	below:				
CLEAR	FRESH	SALTY	SULFUR BLACI	ĸ			
5 MINUTE SHUT	-IN BRADENHEAD	O INTERM	EDIATE				
REMARKS:							
							<del></del> -
Rv	CATIN DO	of t	Witness				
Ву	LI ASE D	PER POR	vv ituess				
	(Positi	on)	<del></del>				