



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-28-06 Operator Maralex Disp. LLC API #30-0 45-33464
Property Name Centerpoint SW Well No. 1 Location: Unit 1 Section 24 Township 31 Range 11
Well Status(Shut-In or Producing) Initial PSI: Tubing 180 Intermediate 0 Casing 329 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min		0	329		
10 min		0	329		
15 min		0	329		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	✓

RCVD NOV28'06
OIL CONS. DIV.

DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH ✓ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

flowed for 8 min. water no gas
pudd on intermediate

By Jeremy Golob
Sr. Engineer
(Position)

Witness Monica Lullaga

E-mail address j.golob@maralexresources.com