



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

RCVD JAN18'07

OIL CONS. DIV.

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 1-18-07 Operator Patina San Juan Inc. API # 30-0 45-26275

DIST. 3

Property Name Lungendorf Well # 3 Location: Unit 0 Sec 34 Twn 31 Rge 13

Land Type:

Well Type:

State _____
Federal _____
Private _____
Indian _____

Water Injection _____
Salt Water Disposal ☒
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): 0 TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 710/braden
Int. Casing Pres. N/A

Pressured annulus up to 342 psi. for 30 mins. Test passed/failed

REMARKS:


Packer set at 3484
held at 341
limit 712

By Danny Wright
(Operator Representative)

Witness Monica Kuehling
(NMOCD)

Production Foreman
(Position)

Revised 02-11-02



Monica Cuckling
Dan Gifford

Lungenda #3

PRINTED IN U.S.A.