

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
Sundry Notices and Reports on Wells

- |  |   |
|--|---|
| <p>1. <b>Type of Well</b><br/>OIL</p> <hr/> <p>2. <b>Name of Operator</b><br/>John F. Staver dba Saquaro Oil Company</p> <hr/> <p>3. <b>Address &amp; Phone No. of Operator</b></p> <hr/> <p><b>Location of Well, Footage, Sec., T, R, M</b><br/>1400' FNL and 1944' FEL; Sec. 3, T-27-N, R-17-W,<br/>Unit G</p> | <p>5. <b>Lease Number</b><br/>I-89-IND-57</p> <p>6. <b>If Indian, All. or Tribe Name</b><br/>Navajo</p> <p>7. <b>Unit Agreement Name</b></p> <hr/> <p>8. <b>Well Name &amp; Number</b><br/>Table Mesa #3</p> <p>9. <b>API Well No.</b><br/>30-045-22005</p> <p>10. <b>Field and Pool</b><br/>Table Mesa Dakota</p> <p>11. <b>County &amp; State</b><br/>San Juan County, NM</p> |
|--|---|

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

- | Type of Submission                                    | Type of Action                                  |  |
|---|---|--|
| <input type="checkbox"/> Notice of Intent             | <input checked="" type="checkbox"/> Abandonment | <input type="checkbox"/> Change of Plans         |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion           | <input type="checkbox"/> New Construction        |
| <input type="checkbox"/> Final Abandonment            | <input type="checkbox"/> Plugging Back          | <input type="checkbox"/> Non-Routine Fracturing  |
|   | <input type="checkbox"/> Casing Repair          | <input type="checkbox"/> Water Shut off          |
|   | <input type="checkbox"/> Altering Casing        | <input type="checkbox"/> Conversion to Injection |
|   | <input type="checkbox"/> Other -                |  |

13. Describe Proposed or Completed Operations

A-Plus Well Service Inc., as contractor, re- entered and then plugged and abandon this well per the attached report.

This work was done for the NMOCD Aztec District Office, contract pending.

14. I hereby certify that the foregoing is true and correct.

Signed William F. Clark Title Contractor Date 3/5/99

(This space for Federal or State Office use)  
APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_  
CONDITION OF APPROVAL, if any: \_\_\_\_\_

# A - PLUS WELL SERVICE, INC.

P.O. BOX 1979  
FARMINGTON, NM 87499  
505-325-2627 • FAX: 505-325-1211

February 25, 1999

---

**Oil Conservation Division**  
State of New Mexico  
1000 Rio Brazos Road  
Aztec, NM 87410

Re: Plug & Abandonment Report      **Table Mesa #3 Well**  
NE, 3, 27N, 17W  
San Juan County, NM

## **Cementing Summary:**

**Plug #1** with 77 sxs Class B cement inside 5-1/2" casing from 700' to 340' to cover Gallup.

**Plug #2** with 55 sxs Class B cement from 159' to surface, circulate good cement out casing valve.

## **Plugging Summary:**

2-23-99 Road rig and equipment to location, RU. NU 8-5/8" flange and BOP; test BOP. PU 4-3/4" bit, bit sub and drill collar. RU P/S and drilling equipment. Drill out 94' cement at surface and then circulate well clean. RD power swivel and RU tongs. TIH with 2-3/8" tubing workstring; found fill at 987'. Circulate hole clean. RU power swivel and start drilling hard cement at 1070'. Drill to 1080'. RD power swivel and circulate well clean. PUH to 700'. RU cementing equipment. Plug #1 with 77 sxs Class B cement inside 5-1/2" casing from 700' to 340' to cover Gallup. TOH with tubing and LD drill collars and bit. Load casing with water. Shut in well and SDFD.

2-24-99 Safety Meeting. Open up well, no pressures. TIH with open ended tubing. Tag cement at 450'. PUH to 159'. Plug #2 with 55 sxs Class B cement from 159' to surface, circulate good cement out casing valve. TOH and LD tubing. RD rig and equipment. ND BOP and wellhead. Cut off 8-5/8" casing. Found cement down 4'. Mix 10 sxs Class B cement and install P&A marker. Move off location. Charlie Perrin with NMOCD on location approving plugging procedures.



