## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX (505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test	6.	14-	07	Opera	ntor	Dugan Production Corp				_API#	30-039-22283					
Property Name	·	А	New I	Dawn		_Well No _	2	Location	: Unit	E	Section	14	Township	24N	Range	5W
Well Status(Sh	ut-ln o	r Prod	ucing)	Initia	al PSI:	Tubing _	0	Intermed	liate		_Casing	3		_Bradenl	nead (	2
OPEN BRADENHEAD AND INTERME PRESSURE Bradenhead Interm  TIME BH Int Csg Int Csg 5 mintues 10 minutes						s	DIATE TO ATMOSPHERE  Steady Flow Surges			FLOW	LY FOR CHARACT			DIATE	-	-
15 minutes	$\vdash$						own to N	lothing						1891	11127	3.
20 minutes							lothing		<del></del>				(%) (%) (%)			Pos
25 minutes	-		_			1	as						2	RECE	IVEL	67
30 minutes				İ		3	sas & Wa	iter					31	<b>ENG</b>	2007	18 18 18
Down to Nothing  20 minutes  25 minutes  Gas  Gas & Water  Water    Fresh   Salty   Sulfur   Black   Black   Black   Black   Sulfur   Black   Black																
5 MINUTE S REMARKS:	нит	-IN		BRAD	ENHE	AD _		_	INTERI	MEDIATE		<del></del>				
	Vo	p	russv	٠٠.												
Ву	Switcher (Position)								Witnes	s						