

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX: (505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 6-12-07 Operator H.K. Keesee API # 30-043-05257  
Property Name Margurite Well No 2 Location Unit N Section 20 Township 23N Range 3W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 75 Intermediate        Casing 75 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS		
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE	
	BH	Int	Csg	Int	Csg				
5 minutes									
10 minutes									
15 minutes									
20 minutes									
25 minutes									
30 minutes									

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water



**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

No pressure

By [Signature]  
Switcher  
(Position)

Witness \_\_\_\_\_