



NEW MEXICO ENERGY, MINERALS and  
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(~~FE~~ OR UIC)

Date of Test 10/6/03 Operator Be & D operating Inc. API # 30-031-20242

Property Name South Hespah Unit Well # 51 Location: Unit E Sec 12 Twn 17 Rge 9

Land Type:

State \_\_\_\_\_  
Federal X  
Private \_\_\_\_\_  
Indian \_\_\_\_\_

Well Type:

Water Injection X  
Salt Water Disposal \_\_\_\_\_  
Gas Injection \_\_\_\_\_  
Producing Oil/Gas \_\_\_\_\_  
Pressure observation \_\_\_\_\_

Temporarily Abandoned Well (Y/N): N TA Expires: \_\_\_\_\_

Casing Pres. \_\_\_\_\_ Tbg. SI Pres. \_\_\_\_\_ Max. Inj. Pres. \_\_\_\_\_  
Bradenhead Pres. 0 Tbg. Inj. Pres. \_\_\_\_\_  
Tubing Pres. \_\_\_\_\_  
Int. Casing Pres. \_\_\_\_\_

Pressured annulus up to \* psi. for \_\_\_\_\_ mins. Test ~~passed~~ failed


REMARKS: \* Well would not pressure up to test  
Well was shut in by operator.

By [Signature]  
(Operator Representative)

Witness [Signature]  
(NMOCD)

(Position)

Revised 02-11-02



GRAPHIC CONTROLS CORPORATION  
BUFFALO, NEW YORK

CHART NO. MC MP-1000

METER \_\_\_\_\_

CHART PUT ON 10:30 A

TAKEN OFF 10:32 A

LOCATION

BC+O operating Div.

REMARKS

South Hospital Unit # 51

API # 30-031-20242

*Donut 7:50 A*  
*BC:R*

PRINTED IN U.S.A.