



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6-8-07 Operator CDX RIO, LLC API #30-039- 22897

Property Name Jicarilla "A" Well No. 8E Location: Unit P Section 17 Township 24N Range 5W

Well Status (Shut-In or Producing) Tubing 70 Intermediate - Casing 53 Bradenhead 13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>Ø</u>		<u>53</u>		
10 minutes	<u>Ø</u>		<u>53</u>		
15 minutes	<u>Ø</u>		<u>53</u>		
20 minutes					
25 minutes					
30 minutes					
				Steady Flow	
				Surges	
				Down to Nothing <u>X</u>	
				Nothing	
				Gas <u>X</u>	
				Gas & Water	
				Water	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE \_\_\_\_\_

REMARKS:

Blew down in 5 seconds



By Duane Harrison  
Field Tech  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_