



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/14/07 Operator CDX RIO, LLC API #30-039- 08154
Property Name JICA #108 Well No. 6 Location: Unit F Section 14 Township 26 Range 5
Well Status (Shut-In or Producing) Tubing 75th Intermediate N/A Casing 160th Bradenhead 2th

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0</u>		<u>160</u>	Steady Flow	
10 minutes	<u>0</u>		<u>160</u>	Surges	
15 minutes	<u>0</u>		<u>160</u>	Down to Nothing <u>X</u>	
20 minutes	<u>0</u>		<u>160</u>	Nothing	
25 minutes	<u>0</u>		<u>160</u>	Gas	
30 minutes	<u>0</u>		<u>160</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 1th INTERMEDIATE _____

REMARKS: Bradenhead; had 2th psi ready, blew down to 0 in - 5 min.

By Ry Harrison Witness _____
Field Tech.
(Position)

E-mail address _____

