



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-12-2007 Operator CDX RIO, LLC API #30-039- 22179

Property Name Jicarilla Cont. 146 Well No. 10E Location: Unit E Section 9 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 93# Intermediate N/A Casing 110# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0#</u>		<u>110#</u>	Steady Flow	
10 minutes	<u>0#</u>		<u>110#</u>	Surges	
15 minutes	<u>0#</u>		<u>110#</u>	Down to Nothing	
20 minutes				Nothing	<u>X</u>
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0# INTERMEDIATE _____

REMARKS: Bradenhead had no pressure upon opening of 1" valve
after 15 minute vent, or vapor.

By WES

Witness NONE

Field Technician

(Position)

E-mail address _____

