

NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-14-2007 Operator CDX RIO, LLC API #30-039- 22482


Property Name Jicarilla Cont. 146 Well No. 31 Location: Unit E Section 10 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 75# Intermediate N/A Casing 120# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u> #		<u>120</u> #
10 minutes	<u>0</u> #		<u>120</u> #
15 minutes	<u>0</u> #		<u>120</u> #
20 minutes			
25 minutes			
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0# INTERMEDIATE _____

REMARKS: Bradenhead had NO pressure or vapor upon opening of 1" valve.

By W. A. [Signature]
Field Technician
(Position)

Witness _____

E-mail address _____