



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**


(Submit 2 copies to above address)

Date of Test 6-14-2007 Operator CDX RIO, LLC API #30-039- 22520  
Property Name Jicarilla Cont. 146 Well No. 11E Location: Unit 0 Section 4 Township 25N Range 5W  
Well Status (Shut-In or Producing) Tubing 74# Intermediate N/A Casing 100# Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>		<u>100</u> #
10 minutes	<u>0</u>		<u>100</u> #
15 minutes	<u>0</u>		<u>100</u> #
20 minutes			
25 minutes			
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

Bradenhead had no pressure or vapor upon opening of  
1" valve.

By W. A.

Witness NONE

Field Technician

(Position)

E-mail address \_\_\_\_\_