



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)


Date of Test June 8, 2007 Operator CDX RIO, LLC API #30-039- 06042

Property Name Jic. Cont. 148 Well No. 13 Location: Unit C Section 15 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 40# Intermediate N/A Casing 55# Bradenhead 31#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>-1#</u>		<u>55#</u>	Steady Flow	
10 minutes	<u>-1#</u>		<u>55#</u>	Surges	
15 minutes	<u>-1#</u>		<u>55#</u>	Down to Nothing	
20 minutes	<u>-1#</u>		<u>55#</u>	Nothing	
25 minutes	<u>-1#</u>		<u>55#</u>	Gas	
30 minutes	<u>-1#</u>		<u>55#</u>	Gas & Water	
				Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD -1# INTERMEDIATE _____

REMARKS:

BH pressured
down to less than 1# after 1" valve was opened.

By WGA
Field Technician
(Position)

Witness NONE

E-mail address _____