



and
NATURAL RESOURCES
DEPARTMENT

1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-21-2007 Operator CDX RIO, LLC API #30-039- 23786
Property Name Jicarilla Cont. 148 Well No. 37 Location: Unit C Section 13 Township 25N Range 5W
Well Status (Shut-In) or Producing) Tubing 180[#] Intermediate N/A Casing 190[#] Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0</u>		<u>190</u> [#]	Steady Flow	
10 minutes	<u>0</u>		<u>190</u> [#]	Surges	
15 minutes	<u>0</u>		<u>190</u> [#]	Down to Nothing	
20 minutes				Nothing	<u>X</u>
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Bradenhead had no pressure or vapor upon opening of
1" valve.

By W. C. H. Witness _____

Field Technician
(Position)

E-mail address _____

