



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test Aug 13, 2007 Operator SH Intervent 1 LTD API # 30-045-29160

Property Name West Bisti 26-13-17 Well # 001 Location: Unit A Sec 17 Twn 26 Rge 13

Land Type:

State _____
Federal ☒
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____
Headhead Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to _____ psi. for _____ mins. Test passed/failed failed

REMARKS:

5 attempts all failed

Top Perf @ 1443'

CIBP @ 1430'

RCVD AUG 13 '07

OIL CONS. DIV.

DIST. 3

By M. Smith
(Operator Representative)

Witness Shelly Cowden
(NMOCD)

Consultant
(Position)

Placed 100' Cement on top of CIBP Per Phone Call from M.L. Smith
will Retest 8/14/07 10:00AM
860-2241 @ 3:00PM
8/13/07

Oil Conservation Division * 1000 Rio Brazos Road * Aztec, New Mexico 87410
Phone: (505) 334-6178 * Fax (505) 334-6170 * <http://www.emnrd.state.nm.us>

